


From Pickup



The black circles or rectangles denote solder points and the empty rectangles where the tab is cut off.